

TRANSPORT EMERGENCY CARD (Road)

UN No. : 1992
ADR CLASS No. 3
ADR PACK GROUP II

LOAD FLAMMABLE LIQUID, TOXIC, N.O.S. (METHANOL, PHENOL) BASIC DRYENE

NATURE OF DANGER

- Highly flammable
- May evaporate quickly
- The vapour may be invisible. The vapour is heavier than air and spreads along ground
- May form explosive mixture with air, particularly in empty uncleaned receptacles
- Corrosive
- The vapour has irritant effect: on eyes, on air passages
- Heating will cause pressure rise, severe risk of bursting and subsequent explosion
- Contact with liquid causes severe damage: to eyes, to skin (skinburns)

PERSONAL PROTECTION

- Goggles giving complete protection to eyes
- Eyewash bottle with clean water
- Two self-standing warning signs, handlamp, warning vest
- Plastic or synthetic rubber gloves. Apron or other light protective clothing. Boots
- Suitable respiratory protection device

GENERAL ACTIONS BY THE DRIVER

- Stop the engine
- No naked lights. No smoking
- Mark roads with self-standing warning signs and warn other road users or passers-by
- Keep public away from danger area. Keep upwind
- Notify police and fire brigade as soon as possible

ADDITIONAL AND/OR SPECIAL ACTIONS BY THE DRIVER

- Any action only if without personal risk
- If practicable: use shovel, broom, small collecting container
- Avoid direct contact with substance
- Stop leaks if without risk
- Use low-sparking handtools and explosion-proof electrical equipment
- Contain or absorb leaking liquid with sand or earth or other suitable material
- If substance has entered a water course or sewer or been spilt on soil or vegetation, advise police
- Prevent liquids entering water courses, sewers, basements and workpits. Vapour may create explosive and corrosive atmosphere
- Warn everybody - Explosion and corrosive hazard

FIRE (information for the driver in case of fire)

- Do not attempt to deal with any fire involving the load

FIRST AID

- If substance has got into the eyes, immediately wash out with plenty of water. Continue treatment until medical assistance is provided
- Remove contaminated clothing immediately and wash affected skin with soap and water
- Seek medical treatment when anyone has symptoms apparently due to inhalation or contact with skin or eyes
- In case of burns immediately cool affected skin as long as possible with cold water
- Persons who have inhaled the fumes produced in a fire may not show immediate symptoms. Patient must be kept under medical supervision for at least 24 hours

SUPPLEMENTARY INFORMATION FOR EMERGENCY SERVICES

- Keep container(s) cool by spraying with water if exposed to fire
- Extinguish with waterspray, foam or dry chemical
- Do not use water jet

ADDITIONAL INFORMATION

Dodge Company Ltd,
Units 11/15 Ardglen Industrial Estate,
Whitchurch, Hampshire,
RG28 7BB, United Kingdom