



**MATERIAL SAFETY DATA SHEET**

**Name:** FORMALDEGONE

**VI. HEALTH HAZARD DATA:** Primary routes of entry: INHALATION.

**Hazard Identification:**

**INHALATION:** High vapor concentrations are irritating to the respiratory tract. May cause headaches and dizziness.

**SKIN:** Hazard is negligible at temperatures between 0°F (-18°C) and 100°F (38°C). Frequent or prolonged contact may cause irritation or dermatitis.

**EYE CONTACT:** Irritation and injury will occur if not removed promptly.

**INGESTION:** Mildly toxic by ingestion.

**Emergency and First Aid Procedures:**

**INHALATION:** Remove person from contaminated area. If breathing has stopped, give artificial respiration. If breathing is difficult, administer oxygen. Contact a physician.

**SKIN:** Remove contaminated clothing (launder before re-use). Wash skin with large amounts of soap and water. If irritation persists, contact a physician.

**EYE CONTACT:** Flush eyes with water for at least 15 minutes. Contact a physician immediately.

**INGESTION:** Do not induce vomiting. Neutralize swallowed product with vinegar solution, fruit juice or another suitable acidic solution. Contact a physician.

**VII. SAFE HANDLING AND USE:**

**Spill Procedures:** Eliminate ignition sources. Soak up with non-combustible absorbent material. Remove absorbent material to a chemical disposal area.

**Waste Disposal:** Improper disposal can cause damage to the environment. Dispose of all material in accordance with federal, state, and local regulations.

**VIII. SPECIAL PROTECTION INFORMATION:**

**Respiratory Protection:** A full-face shield/goggles combination or appropriate respirator, NIOSH/MSHA approved, should be used if exposure limits are exceeded.

**Protective Gloves:** Rubber, neoprene, nitrile, or other waterproof gloves.

**Eye Protection:** Safety goggles for normal use.

**Ventilation:** Local exhaust is recommended whenever this product is used in a confined space or is agitated.

**IX. SPECIAL PRECAUTIONS:**

**Handling and Storage:** Avoid contact with eyes, skin, and clothing. Avoid prolonged breathing of vapor. Do not store for long periods of time below 35°F (2°C) or above 100°F (38°C). Keep containers tightly closed when not in use. Wash thoroughly after handling.